




HANDRAIL PROFILES




HR 1250
1-1/4 FULLROUND




HR 1500
1-3/8 X 1-1/2




HR 1501
1-1/2 X 1-1/2




HR 1502
1-1/2 X 1-1/2




HR 1625
1-7/16 X 1-5/8



HR 1875
1-1/2 X 1-7/8




HR 2000
1-5/8 X 2




HR 2001
1-1/2 X 2


HANDRAIL PROFILES




HR 2289
2.233 X 2.289



HR 2375
2-3/8 X 2-1/4




HR 2376
2-3/8 Round




HR 2377
2-1/4 x 2-3/8


HANDRAIL PROFILES




HR 2500
2-1/4 x 2-1/2



HR 2501
2 x 2-1/2




HR 2750
2-3/8 x 2-3/8




HR 2987
2.631 x 2.987

HANDRAIL PROFILES




HR 3000
2-13/16 x 3




HR 3375
3-1/2 x 3-3/8

HANDRAIL PROFILES



HR 3500
2-1/2 x 3-1/2




HR 3501
2-1/2 x 3-1/2

HANDRAIL PROFILES



HR 3502
1-1/4 x 3-1/2




HR 3502
Assembled


HANDRAIL PROFILES



HR 3503
1 x 3-1/2




HR 3875
1-13/16 x 3-7/8



HR 3876
1-13/16 x 3-7/8


HANDRAIL PROFILES



HR 4000
2 x 4




HR 4500
1-1/2 x 4-1/2




HR 4501
1-1/2 x 4-1/2

HANDRAIL PROFILES



HR 5000
1-1/4 x 5




HR 5001
1-1/4 x 5




HR 5002
1-1/4 x 5


HANDRAIL PROFILES




HR 5003
1-1/4 x 5




HR 5125
1-1/2 x 5-1/8




HANDRAIL PROFILES



HR 5250
1-1/2 x 5-1/4




HR 5500
1-1/2 x 5



HR 5501
1-1/2 x 5-1/2

HANDRAIL PROFILES



HR 5502
1-1/2 x 5-1/2




HR 5503
1-1/2 x 5-1/2



HR 5750
2 x 5-3/4

HANDRAIL PROFILES




HR 6000
 $1\text{-}1/2 \times 6$



HR 6001
 $1\text{-}1/2 \times 6$

HANDRAIL PROFILES



HR 7500
1-1/2 x 7-1/2